


COMPLEX INSPECTION REPORT

Show Most Recent Inspection Only

Raw Coal > Transfer Chutes

TC01 Deflector

Liners



COMPLEX INSPECTION REPORT

Show Most Recent Inspection Only

Liners

Status	Type	Condition	Detail	Action	Inspection By	Age
Liners 4, 5, 6, 7, 9, 10, 11, 12, 13						
Open	Visual	Unknown	[Faults: Other] Unable to sight due to build up on liners		11/10/2022 7:02:00 AM example_admin@pdsglobal.com	0
Liners 1, 20, 21, 22, 24, 25, 27						
Open	Visual	Fault Minor	[Faults: Worn] Appear to be wearing.	Recommend Thickness Testing on next shutdown	11/10/2022 7:49:00 AM example_admin@pdsglobal.com	0
Liners 46, 47, 48, 55, 56, 57						
Open	Visual	Out of Spec	[Faults: Other] Wear Resist used on liners until replacement ones are in stock	Continue to monitor	11/10/2022 8:11:00 AM example_admin@pdsglobal.com	0



Type: Visual, Date: 11/10/2022
Caption: Wear Resist.png

Liners 40, 41, 42, 43, 44, 45, 49, 50, 51, 52, 53, 54						
Closed	Visual	Good			9/11/2021 11:36:19 AM example@pdsglobal.com	334

Chute Structure

Status	Type	Condition	Detail	Action	Inspection By	Age
Door {}						
Open	Visual	Major Fault	[Faults: Corroded] Door is ready to fall off	Requires replacement	10/10/2022 11:07:00 AM example@pdsglobal.com	0

COMPLEX INSPECTION REPORT

Show Most Recent Inspection Only

Jail Bar {}						
Open	Visual	Fault Minor	[Faults: Other] not shutting properly	10/10/2022 11:36:00 AM example@pdsglobal.com	0	
Dust Curtain {}						
Closed	Visual	Good		11/10/2022 8:01:01 AM example_admin@pdsglobal.com	0	
Parent Metal {}						
Open	Visual	Fault Minor	[Faults: Corroded] Existing patches corroded.	Continue to monitor	11/10/2022 8:02:00 AM example_admin@pdsglobal.com	0



Type: Visual, Date: 11/10/2022
Caption:
Chute.png

Show Most Recent Inspection Only

