



FAILURE KPI REPORT FOR IDLER CONFIGURATIONS

Displays an analysis of failures for each idler configuration for the selected business / group / department / area

Filter by Period : (changed between 16/07/2017 and 16/08/2017)

Summary of Idler Failures by Idler Configuration



Summary of Idler Failures by Idler Configuration			Total
2 Roll Return	Collapsed Bearing	CV308	8
		Total	8
	Noisy	CV08	146
		CV09	1
		CV10	4
		CV11	14
		CV308	9
		CV308 Tripper	2
		CV309	1
		Total	177
	Out of Bracket	CV08	1
		Total	1
	Preventive Maintenance	CV09	5
		CV11	1
		CV308	3
		CV309	1
		Total	10
	Split Shell	CV09	1
		CV309	1
		Total	2
	Worn Shell	CV08	2
CV09		1	
CV10		7	
CV308		1	
CV309		2	
Total		13	

FAILURE KPI REPORT FOR IDLER CONFIGURATIONS



Displays an analysis of failures for each idler configuration for the selected business / group / department / area

Filter by Period : (changed between 16/07/2017 and 16/08/2017)

Summary of Idler Failures by Idler Configuration			Total
2 Roll Return		Total	211
2 Roll Return Flat	Noisy	CV11	1
		CV308	1
		CV309	4
		Total	6
Total			6
2 Roll Return Inverted	Noisy	CV11	2
		Total	2
		Total	
3 Roll Trough	Collapsed Bearing	CV08	2
		CV08 Tripper	1
		CV09	1
		CV10	1
		CV11	2
		CV11 Tripper	3
		CV308	1
		CV309	1
		Total	12
	Noisy	CV08	178
		CV08 Tripper	31
		CV09	2
		CV10	8
		CV11	26
		CV308	15
		CV308 Tripper	26
		CV309	25
		Total	311
	Other	CV308	3
		Total	3
	Out of Bracket	CV11	1
		Total	1
	Preventive Maintenance	CV08	10
		CV08 Tripper	2
		CV09	2
		CV11	14
		CV308	8
		Total	36
	Seized	CV08	6
		CV10	30

FAILURE KPI REPORT FOR IDLER CONFIGURATIONS



Displays an analysis of failures for each idler configuration for the selected business / group / department / area

Filter by Period : (changed between 16/07/2017 and 16/08/2017)

Summary of Idler Failures by Idler Configuration			Total
3 Roll Trough	Seized	CV11	17
		Total	53
	Worn Shell	CV08	2
		CV09	7
		CV10	3
		CV11	7
		CV308	1
		CV309	1
		Total	21
	Total		
Flat Return	Split Shell	CV09	1
		Total	1
	Worn Shell	CV09	1
		Total	1
Total			2
Total			658