

REPLACEMENT REPORT FOR IDLER STRUCTURE

Displays a list of outstanding idler structure due for replacement for the selected business / group / department / area

Failure Priorities : (All) ; Days in Failure (>) : 0



Mine C > OHP > Conveyors > CV30


Structure Replacements: **12**

Frame	At Risk	CT	Other / -	Tag No	Structure Type	Pri	Failure Type	Comments (Access Issues)	Stockcode / Part No.	Laid Out	Changed	Days in Failure
36				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller		No	<input type="checkbox"/>	55
45				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller		No	<input type="checkbox"/>	55
62				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55
70				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55
75				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in the past		No	<input type="checkbox"/>	55
76				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55
77				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55
78				iPad	Trough Inline Frame	3	Worn Spindle Holder			No	<input type="checkbox"/>	13
86				iPad	Trough Inline Frame	3	Worn Spindle Holder			No	<input type="checkbox"/>	13
88				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55
92				iPad	Trough Inline Frame	3	Worn Spindle Holder			No	<input type="checkbox"/>	13
98				iPad	Trough Inline Frame	2	Damaged	Damaged due to collapsed roller in past		No	<input type="checkbox"/>	55

REPLACEMENT REPORT FOR IDLER STRUCTURE

Displays a list of outstanding idler structure due for replacement for the selected business / group / department / area

Failure Priorities : (All) ; Days in Failure (>) : 0



Frame: 77
Trough Inline Frame



Frame: 88
Trough Inline Frame



Frame: 98
Trough Inline Frame

Failure Type Priorities	
Priority	Description
1	Requires attention within 24 hours
2	Requires attention within 1 week
3	Requires attention within 4 weeks
4	Requires replacement in the next outage

Picking List	
Part No.	Number Needed
-	12

REPLACEMENT REPORT FOR IDLER STRUCTURE

Displays a list of outstanding idler structure due for replacement for the selected business / group / department / area

Failure Priorities : (All) ; Days in Failure (>) : 0



Frame: 36
Trough Inline Frame



Frame: 45
Trough Inline Frame



Frame: 62
Trough Inline Frame



Frame: 70
Trough Inline Frame



Frame: 75
Trough Inline Frame



Frame: 76
Trough Inline Frame