AT FAULT INSPECTIONS

Unrectified Only, Show Most Recent Inspection Only

Raw Coal > Conveyors

CV102

BELT JOINTS

Status	Туре	Condition	Detail	Action	Inspection By	Age
EQUIPMENT	T: (1) SPLICE (BRAND: RELIA	BLE 100)			
OPEN	Visual	MAJOR FAULT	Task: Unplanned Inspections[Faults: Delaminating Butt Joint]Section in middle lifting 150mm across	Requires repair.	10/04/2018 7:54:58 AM demo@pdsonline.com.au	0
BELT SEC	TIONS					
Status	Туре	Condition	Detail	Action	Inspection By	Age
EQUIPMENT	Γ: (1) PN640/4	1200 6.0+2.0 M	GRADE (LENGTH (M): 88)			
OPEN	Visual	FAULT MINOR	Task: Unplanned Inspections[Faults: Wear in Skirt Line][Top:] Continued wear in skirt lines both sides.	Continue to monitor.	10/04/2018 7:53:46 AM demo@pdsonline.com.au	0
		GOOD	[Bottom:]			
CLEANING	SYSTEMS		•	-		
Status	Туре	Condition	Detail	Action	Inspection By	Age
EQUIPMENT	T: (1) PRIMAR	CLEANER (LC	DCATION: HEAD , MANUFACTURER: ESS)			
OPEN	Visual	MAJOR FAULT	Task: Unplanned Inspections[Faults: Cushion Damaged]2nd cushion from RHS broken	Requires replacement at next available opportunity to ensure it does not end up contacting belt.	27/03/2018 10:06:47 AM demo@pdsonline.com.au	13
EQUIPMENT	T: (5) DIAGON	AL PLOUGH (LO	DCATION: TAIL, MANUFACTURER: ESS)			
OPEN	Visual	OUT OF SPEC	Task: Unplanned Inspections[Faults: Nose sitting up]Only contacting blades on edges.	Requires adjustment	10/04/2018 7:52:47 AM demo@pdsonline.com.au	0
PULLEYS						
Status	Туре	Condition	Detail	Action	Inspection By	Age
EQUIPMENT	Γ: (1) HEAD (L	AGGING TYPE:	CERAMIC)			_
		1				

OPEN	Visual	OUT OF SPEC	Task: Unplanned Inspections [Faults: Lagging Delaminated]	10/04/2018 7:16:55 AM demo@pdsonline.com.au	0
			Lagging delaminated on LHS edge.		



AT FAULT INSPECTIONS

Unrectified Only, Show Most Recent Inspection Only

RHS servo roller collapsed.

CV102

PULLEYS

Status	Туре	Condition	Detail	Action	Inspection By	Age	
EQUIPMENT: (2) TAIL (LAGGING TYPE: POLY STRIP)							
OPEN	Visual	FAULT MINOR	Task: Unplanned Inspections [Faults: Lagging wear on belt line] Lagging beginning to wear on belt line RHS.	Contiune to monitor.	10/04/2018 7:18:11 AM demo@pdsonline.com.au	0	
TRACKING DEVICES							
Status	Туре	Condition	Detail	Action	Inspection By	Age	
EQUIPMENT: (1) TROUGH TRACKER (FRAME: 21312, MODEL: 12321)							
OPEN	Visual	OUT OF SPEC	Task: Unplanned Inspections [Faults: Servo roller bearing collapsed]	Requires replacement.	10/04/2018 7:56:13 AM demo@pdsonline.com.au	0	



AT FAULT INSPECTIONS

Unrectified Only, Show Most Recent Inspection Only



