


LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Mine Operations, Raw Coal, Transfer Chutes, T2 Transfer



Never	Adjusted	Replaced <= 12 Weeks	Replaced <= 24 Weeks	Replaced <= 36 Weeks	Replaced > 36 Weeks
-------	----------	----------------------	----------------------	----------------------	---------------------

Replacements Map Legend

Information

Details 169 Records(s)

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145121 (5 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601A	1	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601A	1	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601A	1	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
601A	1	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
601A	1	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Damaged	1

Part Number: LN145122 (15 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
RECT-001	2	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
RECT-001	2	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
RECT-001	2	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
RECT-001	2	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
RECT-001	2	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
RECT-001	31	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
RECT-001	31	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
RECT-001	32	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
RECT-001	32	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
RECT-001	48	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
RECT-001	49	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145122 (15 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
RECT-001	65	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
RECT-001	66	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
RECT-001	74	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
RECT-001	75	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

Part Number: LN145123 (5 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601B	3	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601B	3	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601B	3	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
601B	3	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
601B	3	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

Part Number: LN145124 (63 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
SQU-001	4	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
SQU-001	4	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	4	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
SQU-001	4	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
SQU-001	4	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
SQU-001	5	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145124 (63 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
SQU-001	5	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	5	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
SQU-001	5	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
SQU-001	5	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
SQU-001	6	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
SQU-001	6	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	6	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
SQU-001	6	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
SQU-001	6	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
SQU-001	10	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
SQU-001	10	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	10	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
SQU-001	11	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
SQU-001	11	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	11	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	
SQU-001	17	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
SQU-001	17	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
SQU-001	17	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145124 (63 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
SQU-001	21	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
SQU-001	21	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	22	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
SQU-001	22	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	26	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	26	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	26	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	27	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	27	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	27	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	33	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
SQU-001	33	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	34	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
SQU-001	34	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	38	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	38	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	38	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	40	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145124 (63 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
SQU-001	40	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	41	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
SQU-001	41	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
SQU-001	45	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	45	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	45	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	46	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	46	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	46	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	50	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
SQU-001	51	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
SQU-001	55	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	55	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	55	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
SQU-001	57	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
SQU-001	58	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
SQU-001	67	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
SQU-001	68	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145124 (63 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
SQU-001	72	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
SQU-001	72	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
SQU-001	72	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145127 (5 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601C	7	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601C	7	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601C	7	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Damaged	
601C	7	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	2/05/2022	Worn Liner deteriorating visually	
601C	7	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

Part Number: LN145128 (2 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601D	8	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
601D	8	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	

Part Number: LN145129 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601E	9	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601E	9	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601E	9	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145132 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601F	12	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601F	12	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601F	12	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

Part Number: LN145133 (2 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601G	13	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
601G	13	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	

Part Number: LN145136 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601J	16	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601J	16	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601J	16	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

Part Number: LN145138 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601K	18	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	13/06/2019	Damaged	
601K	18	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	22/11/2020	Worn	
601K	18	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Worn	

Part Number: LN145139 (6 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
RECT-002	19	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145139 (6 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
RECT-002	19	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
RECT-002	20	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	4/05/2021	Damaged	
RECT-002	20	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	5/12/2022	Worn	
RECT-002	82	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	
RECT-002	83	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

Part Number: LN145145 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601N	25	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601N	25	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601N	25	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145148 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601O	28	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601O	28	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601O	28	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145157 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601T	37	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601T	37	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145157 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601T	37	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145159 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601U	39	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601U	39	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601U	39	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145164 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601V	44	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601V	44	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601V	44	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145167 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601W	47	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601W	47	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601W	47	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145174 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601X	54	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601X	54	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601X	54	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145176 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601Y	56	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601Y	56	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601Y	56	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145181 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
601Z	61	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
601Z	61	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
601Z	61	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145182 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602A	62	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602A	62	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602A	62	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145183 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602B	63	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602B	63	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602B	63	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145184 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602C	64	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602C	64	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602C	64	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145191 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602D	71	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602D	71	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602D	71	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

Part Number: LN145193 (3 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602E	73	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602E	73	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602E	73	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145198 (4 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602F	78	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602F	78	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602F	78	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
602F	78	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Missing Liners missing at bottom	2

Part Number: LN145199 (4 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602G	79	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	24/12/2021	Worn	
602G	79	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	21/05/2022	Worn	
602G	79	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	1/04/2023	Scheduled Replacement	
602G	79	50	Duaplate	Larrys Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	6/07/2023	Missing Liners missing at bottom	2

Part Number: LN145200 (1 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602H	80	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

Part Number: LN145201 (1 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602J	81	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

LINER REPLACEMENTS REPORT

Displays a representation of and list of liners by part number for the selected business / group / department / area (replaced between 21/07/2013 and 21/07/2023)

Part Number: LN145204 (1 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602K	84	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	

Part Number: LN145205 (1 records)

Item No.	PDS No.	Thickness	Material Type	Manufacturer	Fixing Type	Backing Material	Backing Thickness	Marking Plan Drawing	Liner Detail Drawing	Removal Date	Reason for Replacement / Comments	Photo #
602L	85	50	Duaplate	ACME Liners	Stud	Mild Steel	13	MP-1067543	DD-984325	12/09/2022	Worn	



#1-
21/07/2023 11:13:22 AM



#2- Liners missing at bottom
21/07/2023 10:55:13 AM