

REPLACEMENT REPORT FOR IDLERS

Displays a list of idlers replaced for the selected business / group / department / area

Failure Priorities : (All) ; Filter by Period : (changed between 9/08/2017 and 16/08/2017)



Mine C > OHP > Conveyors > CV30

Idler Replacements: **48**

Idler Type (Manufacturer)	Frame	At Risk	Other / -	Failure Type	Maintenance Activity	Comments (Work Order Number)	Stockcode / Part No.	Tagged	Changed	Days in Failure
3 Roll Trough - LHS Steel - Line	4			Other	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - LHS Impact Rubber Ringed - Line	5			Other	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - RHS Impact Rubber Ringed - Line	5			Other	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - RHS Steel - Line	5			Seized		427754079	10852959	19/07/2017	9/08/2017	20
3 Roll Trough - LHS Impact Rubber Ringed - Double Set - Tail Side	6			Noisy		427754079	10852959	19/07/2017	9/08/2017	20
3 Roll Trough - Centre Impact Rubber Ringed - Line	6			Worn Shell		427754079	10852959	22/06/2017	9/08/2017	47
3 Roll Trough - RHS Impact Rubber Ringed - Line	6			Noisy		needs checking both rollers (double framed) 427754079	10852959	22/06/2017	9/08/2017	47
3 Roll Trough - RHS Impact Rubber Ringed - Line	7			Other	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - LHS Impact Rubber Ringed - Line	7			Other	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - LHS Impact Rubber Ringed - Line	8			Seized	Preventive Maintenance	not moving needs checking when isolated 427754079	10852959	1/06/2017	9/08/2017	68
3 Roll Trough - RHS Impact Rubber Ringed - Double Set - Head Side	8			Seized		427754079	10852959	19/07/2017	9/08/2017	20
3 Roll Trough - LHS Steel - Double Set - Tail Side (CPS)	13			Seized	Shutdown Planned Maintenance	427754079	10852959	16/06/2017	9/08/2017	53
3 Roll Trough - RHS Steel - Line (CPS)	50			Noisy	Shutdown Planned Maintenance	427754079	10852959	16/06/2017	9/08/2017	53
3 Roll Trough - LHS Steel - Line (CPS)	50			Noisy	Shutdown Planned Maintenance	427754079	10852959	16/06/2017	9/08/2017	53

REPLACEMENT REPORT FOR IDLERS

Displays a list of idlers replaced for the selected business / group / department / area

Failure Priorities : (All) ; Filter by Period : (changed between 9/08/2017 and 16/08/2017)



Mine C > OHP > Conveyors > CV30

Idler Replacements: **48**

Idler Type (Manufacturer)	Frame	At Risk	Other / -	Failure Type	Maintenance Activity	Comments (Work Order Number)	Stockcode / Part No.	Tagged	Changed	Days in Failure
3 Roll Trough - Centre Steel - Line	50			Collapsed Bearing		roller has collapsed and wearing into the frame. still rotating, keep an eye out 427754079	10852959	16/06/2017	9/08/2017	53
3 Roll Trough - Centre Steel - Line (CPS)	73			Collapsed Bearing		427754079	10852959	14/07/2017	9/08/2017	25
3 Roll Trough - RHS Steel - Line (CPS)	73			Noisy	Shutdown Planned Maintenance	427754079	10852959	14/07/2017	9/08/2017	25
3 Roll Trough - LHS Steel - Line (CPS)	73			Noisy	Shutdown Planned Maintenance	427754079	10852959	14/07/2017	9/08/2017	25
2 Roll Return - RHS Steel - Line (CPS)	79			Preventive Maintenance	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Steel - Line (CPS)	79			Preventive Maintenance	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
3 Roll Trough - Centre Steel - Line	79			Collapsed Bearing	Shutdown Planned Maintenance	damaged frame. keep eye on roller, still spinning 427754079	10852959	22/06/2017	9/08/2017	47
3 Roll Trough - LHS Steel - Line	79			Preventive Maintenance	Shutdown Planned Maintenance	427754079	10852959	22/06/2017	9/08/2017	47
3 Roll Trough - RHS Steel - Line	79			Preventive Maintenance	Shutdown Planned Maintenance	427754079	10852959	22/06/2017	9/08/2017	47
2 Roll Return - RHS Rubber Lagged - Line (CPS)	82			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	82			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - RHS Rubber Lagged - Line (CPS)	85			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	85			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	87			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - RHS Rubber Lagged - Line (CPS)	87			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53

REPLACEMENT REPORT FOR IDLERS

Displays a list of idlers replaced for the selected business / group / department / area

Failure Priorities : (All) ; Filter by Period : (changed between 9/08/2017 and 16/08/2017)



Mine C > OHP > Conveyors > CV30

Idler Replacements: **48**

Idler Type (Manufacturer)	Frame	At Risk	Other / -	Failure Type	Maintenance Activity	Comments (Work Order Number)	Stockcode / Part No.	Tagged	Changed	Days in Failure
2 Roll Return - RHS Rubber Lagged - Line (CPS)	95			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	95			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	16/06/2017	9/08/2017	53
2 Roll Return - LHS Steel - Line (CPS)	97			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	14/07/2017	9/08/2017	25
2 Roll Return - RHS Steel - Line (CPS)	97			Worn Shell	Shutdown Planned Maintenance	427754079	10853229	14/07/2017	9/08/2017	25
3 Roll Trough - RHS Steel - Line	101			Preventive Maintenance	Shutdown Planned Maintenance	centre one has been changed but wings haven't 427754079	10852959	22/06/2017	9/08/2017	47
3 Roll Trough - LHS Steel - Line	101			Noisy	Shutdown Planned Maintenance	centre roller has been changed but wings haven't 427754079	10852959	22/06/2017	9/08/2017	47
2 Roll Return - RHS Rubber Lagged - Line	107			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	22/06/2017	9/08/2017	47
2 Roll Return - LHS Rubber Lagged - Line	107			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	22/06/2017	9/08/2017	47
2 Roll Return - RHS Rubber Lagged - Line (CPS)	110			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	110			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - RHS Rubber Lagged - Line (CPS)	112			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	112			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	115			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - RHS Rubber Lagged - Line (CPS)	115			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53

REPLACEMENT REPORT FOR IDLERS

Displays a list of idlers replaced for the selected business / group / department / area

Failure Priorities : (All) ; Filter by Period : (changed between 9/08/2017 and 16/08/2017)



Mine C > OHP > Conveyors > CV30

Idler Replacements: **48**

Idler Type (Manufacturer)	Frame	At Risk	Other / -	Failure Type	Maintenance Activity	Comments (Work Order Number)	Stockcode / Part No.	Tagged	Changed	Days in Failure
2 Roll Return - RHS Rubber Lagged - Line (CPS)	117			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - LHS Rubber Lagged - Line (CPS)	117			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	16/06/2017	9/08/2017	53
2 Roll Return - LHS Steel - Line	120			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	7/07/2017	9/08/2017	32
2 Roll Return - RHS Steel - Line	120			Worn Shell	Shutdown Planned Maintenance	427754079	10853232	7/07/2017	9/08/2017	32
Flat Return Steel - Line	126			Worn Shell	Shutdown Planned Maintenance	427754079		7/07/2017	9/08/2017	32