REPLACEMENT REPORT FOR IDLERS

Displays a list of outstanding idlers due for replacement for the selected business / group / department / area

Failure Priorities: (All); Days in Failure (>): 0



Idler Replacements: 5

Mine C > OHP > Conveyors > CV30

Frame	At Risk	СТ	Othe	er / -	Tag No.	Idler Type (Manufacturer)	Pri	Failure Type	Comments (Access Issues)	Stockcode / Part No.	Laid Out	Changed	Days in Failure
33					iPad	2 Roll Return - RHS Steel - Line (CPS)	3	Worn Shell		10853229	No		6
33					iPad	2 Roll Return - LHS Steel - Line (CPS)	3	Worn Shell		10853229	No		6
53					iPad	2 Roll Return - LHS Steel - Line (CPS)	3	Noisy		10853229	No		6
53					iPad	2 Roll Return - RHS Steel - Line (CPS)	3	Noisy		10853229	No		6
127					iPad	3 Roll Trough - Centre Steel - Line	3	Worn Shell		10852959	No		28

Failure Type Priorities						
Priority	/ Description					
1	Requires attention within 24 hours					
2	Requires attention within 1 week					
3	Requires attention within 4 weeks					
4	Requires replacement in the next outage					

Picking List								
Part No.	Туре	(L) Dia	(J) Face	(N) Shaft	Number Needed			
10852959	Steel				1			
10853229	Steel				4			