

# IDLER FAILURES BY FRAME NUMBER

Displays idler failures along the length of the conveyor for the selected business / group / department / area





Filter by Period : (tagged between 16/08/2016 and 16/08/2017)

Idler Type: (All) / Failure Type: (All) / Idler Position Group: (All)



Mine C > TLO > Conveyors > CV254

Zoom : -10 to 1000 frames



Number of frames on conveyor: 1000 / Total failures during period: 2834